

Navajo Regional Director's Road Condition Report



IAM 82-8209

	Office: Chinle DOT Road Maintenance Location: Chinle Agency, Chinle, Arizona Telephone No: 928-674-5175 Fax No: 928-674-5184
Date: Thursday, January 26, 2017 Time: 3:30 PM Reported By Chinle DOT Staff	
Weather Condition:	Currently: Cloudy, scattered snow flurries (in-law chasers) at 36°
Snow Depth and/or Rainfall (by Districts):	
District 4 Pinon, Forest Lake, Black Mesa Blue Gap, Whippoorwill, Hard Rocks	Snow 4" to 8"; Black Mesa- 2"-3"; snow drifts 1' Snow 3" to 7"; snow melting beginning to get muddy
District 10 Many Farms, Rough Rock, Round Rock, Chinle & Nazlini	M.F., Rough Rock, Round Rock - No snow; Nazlini: Snow 1/2" to 1 1/2"; some muddy conditions
District 11 Del Muerto, Tsaile Lukachukai, Tsaile, Wheatfields Luka base to Buffalo Pass	Snow 2" to 3" Snow 2" to 3" Snow 2" to 3"
Conditions of Paved Roads (by Districts):	
District 4 Pinon, Forest Lake Blue Gap, Whippoorwill, Hard Rocks	98% -100% clear of snow and ice 99% -100% clear of snow and ice
District 10 Many Farms, Rough Rock, Round Rock, Chinle & Nazlini	M.F., Rough Rock, Round Rock - 100% clear of snow and ice. Nazlini - mostly clear except on the mesa icy patches
District 11 Del Muerto, Tsaile, Luka, Tsaile, Wheatfields Luka base to Buffalo Pass	Some icy patch toward agency line. N13 Road Closed; NDOT to begin snow/ice removal 1/27/17 (may be)
Conditions of Earth Roads (by Districts):	
District 4 Pinon, Forest Lake Blue Gap, Whippoorwill, Hard Rocks	Snow and partial muddy; routes are being graded Snow and partial muddy; routes are being graded
District 10 Many Farms, Rough Rock, Round Rock, Chinle & Nazlini	Freeze and thaw cycle; mostly clear of snow and ice
District 11 Del Muerto, Tsaile, Luka, Tsaile, Wheatfields Luka base to Buffalo Pass	Freeze and thaw cycle; routes are being graded Freeze and thaw cycle; mostly frozen, some cleared of snow and ice
Location of Agency and Other RM Crews (by Districts)	Chinle Agency RM crew on paved and earth routes. NDOT assisting with paved routes
Road Closures:	N13 - Buffalo Pass Closed. NDOT to begin removal 1/27/2017
School Closures:	None
Emergency Activities:	Navajo Nation Declaration of Emergency; Snow and Ice Removal
Remarks:	
Has Information been provided to Agency BIA-DOT Manager?	Yes
Has Information been provided to the Navajo Region Director?	Yes
Has this information been provided verbally to Navajo Region Safety?	No

Navajo Regional Director's Road Condition Report



IAM 82-8209

Office: Eastern DOT	
Location: Marino Lake and Borrego Pass	
Telephone No: 505-786-6039	Fax No: 505-786-6188

Date: 1/26/2017 Time: 3:00 PM Reported By: Robert Babbitt	
Weather Condition: 18 degrees Overcast, Breezy	
Snow Depth and/or Rainfall (by Districts): No new snow in Eastern	Work Completed One crew completed grading 491 ,492, 493, 494, 7113, 7111, 7054, 7149, 7053 and 11. Second crew completed grading 483, 489, 486, 485, 482 and 481
Conditions of Paved Roads (by Districts): South of Gallup Mariano Lake N49, N11, N703- Mostly clear and dry, patches of shush Borrego N48S and N48N- Clear Pintado N9E, N705, N474- Mostly clear and dry Standing Rock N9W, N7057, N7120- Clear and Dry To'Hajiile N56- Clear and Dry Alamo N55- Clear and Dry	
Conditions of Earth Roads (by Districts):	Earth Roads have mud in all Districts
Location of Agency and Other RM Crews (by Districts):	Completed Snow removal in Mariano Lake and Borrego Districts
Road Closures:	All paved roads open
School Closures:	None
Emergency Activities:	None
Remarks:	Crews work 14 hrs to complete snow removal
Has Information been provided to Agency BIA-DOT Manager? YES, by email. Has Information been provided to the Navajo Region Director? YES, by email. Has this Information been provided verbally to Navajo Region Safety? Yes, sent by email	

Navajo Regional Director's Road Condition Report



IAM 82-8209

	Office: <u>WNA - DOT Maintenance</u> Location: <u>Tuba City, Az.</u> Telephone No: <u>928 - 283 - 2300</u> Fax No: <u>928 - 283 - 4658</u>
Date: Jan 26, 2017 Time: 4;30 Reported By: Randy Luaghter	
Weather Condition:	cloudy and cold
Snow Depth and/or Rainfall (by Districts):	Shonto area 7" of snow
Conditions of Paved Roads (by Districts):	Dist 3 Kiabeto snow, Dist 2 Shono 7" of snow, Dist 1 Coppermine Snow
Conditions of Earth Roads (by Districts):	Wet/ Muddy
Location of Agency and Other RM Crews (by Districts):	One Grader in Dist 2, One plow from Dist 3 on N16, and One Plow in Dist 5.
Road Closures:	NONE
School Closures:	No reports.
Emergency Activities:	
Remarks: One snow plow on N16 snow operation, and Dne in the dist 2 starting snow removal earth roads	
Has Information been provided to Agency BIA-DOT Manager? <u>Yes</u> Has Information been provided to the Navajo Region Director? <u>Yes</u>	


Navajo Regional Director's Road Condition Report



IAM 82-8209

Office: Fort Defiance - DOT Maintenance
 Location: Fort Defiance, Az.
 Telephone No: 928 - 729 - 7222 Fax No: 928 - 729 - 7225

Date: 26-Jun-17
 Time: 4.30 PM
 Reported By: Maintenance Supervisor



Weather Condition:
 Over Cast Cold 30 deg

Snow Depth and/or Rainfall (by Districts): Dist 7; Dist 14;
 Dist 17; Dist 18;

Dist 7:
 Dist 14:
 Dist 17:
 Dist 18: 6" to 12" of snow

Conditions of Paved Roads (by Districts):

N12 still has slush and icy spots

Conditions of Earth Roads (by Districts):

All Muddy condition

Location of Agency and Other RM Crews (by Districts):

Road Closures:

None

School Closures:

None

Emergency Activities:

snow & icy control on N12 flat blading on N203, N112, N9001

Remarks:

We have a grader stuck on N9073, N100/N12 signal fixed

Has Information been provided to Agency BIA-DOT Manager?	Yes
Has Information been provided to the Navajo Region Director?	Yes

Navajo Regional Director's Road Condition Report



IAM 82-8209

Office: Shiprock DOT	
Location: District 9, 12 & 13	
Telephone No: 505-368-3341	Fax No: 505-368-3348

Date: Thursday, January 26, 2017	
Time: 3:40 PM	
Reported By: Mr. Anderson Blatchford	

Weather Condition: Shiprock 30⁰ F. Partly Cloudy, Wind Gusts 16 to 22 mph, cold, and visibility 10 miles

Snow Depth and/or Rainfall (by Districts):

- District 9:** Aneth, Sweet Water and Rock Point dry fair driving
- District 12:** Top of N-13 Buffalo Pass, MP17 to MP6, 16-18 inches accumulation snow and icy conditions, road is closed
- District 12:** Red Valley and Cove area dry fair driving
- District 13:** Shiprock and Upper Fruitland dry fair driving
- District 13:** Burnham, Sheep Spring, Newcomb, Toadlena, and Sanostee dry fair driving

Conditions of Paved Roads (by Districts):

- District 9: N-12, N-5114, and N-35 - dry and visibility 10 miles
- District 12: BIA N-13 - MP15 to MP5, 14-16-inches at base of snow and icy conditions closed roadway and visibility 2,000 ft.
- District 12: BIA N-33, N-13 lower, N-34, N-19, N-5010 and N-5000 - dry and visibility 10 miles
- District 13: N-5 and N36 - dry and visibility 10 miles

Conditions of Earth Roads (by Districts):	District 9, 12 and 13 all earth road are muddy
---	--

Location of Agency and Other RM Crews (by Districts):	District 12 - N-13 crew in the field,
---	---------------------------------------

Road Closures:	N-13 Buffalo Pass mountain pass and reported to radio station KNDN
----------------	--

School Closures: Due to Muddy or Snow conditions	None Reported
--	---------------

Emergency Activities:	None Reported
-----------------------	---------------

Remarks:	
----------	--

Has Information been provided to Agency BIA-DOT Manager?	YES, by email.
Has Information been provided to the Navajo Region Director?	YES, by email.
Has this Information been provided verbally to Navajo Region Safety?	YES, sent by email to ACTING Safety Officer.